

Effective: 01/01/2021 to 26/11/2024

Display Action Officer: No

Site: KITCHENER AVENUE (10801272)

Site: KITCHENER AVENUE (10801272)

Locality: DERBY, DERBY CITY

Area: No code allocated

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,001.00	Asset - Locn.:	U10801272/10 - FROM COLERIDGE STREET TO BROWNING		Feature Type: Single 2-Lane Carriageway		Area: No code allocated	
Batch:	20120694 - Inspection Batch		Route: NOR6M-2				Date: 04/09/2024	
20062046	1x FW patch (Not within current fw scheme)	04/09/2024	81 and 79	FW03 ph <25 fast deterioration	Internal		Committed	20061933
20062047	2x FW patch (Not within current fw scheme)	04/09/2024	Outside 72/ 74	FW03 ph <25 fast deterioration	Internal		Committed	20061932
Batch:	20114132 - Inspection Batch		Route: NOR6M-2				Date: 09/04/2024	
No actionable defects found								
Batch:	20109342 - Inspection Batch		Route: Ad Hoc Route				Date: 09/01/2024	
20057896	2 x carriageway patches (Enquiry 20031467)	09/01/2024	Street: Kitchener Avenue Location: Outside 84 and 80	CW19 Cway Followup perm repai	Internal		Committed	20057778
Batch:	20109341 - Inspection Batch		Route: Ad Hoc Route				Date: 09/01/2024	
20057895	Make safe 1 x carriageway pothole (Enquiry 20031467)	09/01/2024	Street: Kitchener Avenue Location: outside 84	CW01 pothole >= 40	Internal		Committed	20057777
Batch:	20105937 - Ad Hoc Inspection Batch		Route: Ad Hoc Route				Date: 20/10/2023	
20056710	Capital Programme FW Resurfacing 2024/25 - HEM **inspectors make safe's only please** (Enquiry 10022358)	20/10/2023	Sinfin Lane to Dryden Street	FW13 fretting	Internal		Committed	20056592
Batch:	20105213 - Inspection Batch		Route: NOR6M-2				Date: 10/10/2023	
No actionable defects found								
Batch:	20098558 - Inspection Batch		Route: NOR6M-2				Date: 15/05/2023	
20054557	Make safe 1x CW pothole	15/05/2023	Outside 78	CW01 pothole >= 40	Internal		Committed	20054437
20054556	1x CW patch	15/05/2023	Outside 78	CW19 Cway Followup perm repai	Internal		Committed	20054438
Batch:	20090718 - Inspection Batch		Route: NOR6M-2				Date: 01/12/2022	
20051512	Fw patch	01/12/2022	O/S 5	FW03 ph <25 fast deterioration	Internal		Committed	20051382
Batch:	20090634 - Inspection Batch		Route: Ad Hoc Route				Date: 30/11/2022	
20051472	Fw patch	30/11/2022	O/S 69	FW03 ph <25 fast deterioration	Internal		Committed	20051342
Batch:	20090047 - Inspection Batch		Route: Ad Hoc Route				Date: 17/11/2022	
20051308	Create a channel at the side of the speed hump to allow ponding water to flow down the road, see opposite side for reference. (Enquiry 20026521)	17/11/2022	Street: Kitchener Avenue Location: Outside 84	FW11 stndg water >=25 >1/4<1/2	Internal		Committed	20051176
Batch:	20089301 - Inspection Batch		Route: Ad Hoc Route				Date: 27/10/2022	
20051059	1 x carriageway patch (Enquiry 20026299)	27/10/2022	Street: Kitchener Avenue Location: Outside no 78 / 80	CW19 Cway Followup perm repai	Internal		Committed	20050924
Batch:	20089300 - Inspection Batch		Route: Ad Hoc Route				Date: 27/10/2022	
20051058	Make safe 4 x carriageway potholes (Enquiry 20026299)	27/10/2022	Street: Kitchener Avenue Location: Outside no 78 / 80	CW01 pothole >= 40	Internal		Committed	20050923

Effective: 01/01/2021 to 26/11/2024

Display Action Officer: No

Site: KITCHENER AVENUE (10801272)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,001.00	Asset - Locn.: U10801272/10 - FROM COLERIDGE STREET TO BROWNING		Feature Type: Single 2-Lane Carriageway			Area: No code allocated	
Batch:	20083156 - Inspection Batch			Route: NOR6M-2				Date: 10/06/2022
	No actionable defects found							
Batch:	20076371 - Inspection Batch			Route: NOR6M-2				Date: 31/01/2022
	No actionable defects found							
Batch:	20069680 - Inspection Batch			Route: NOR6M-2				Date: 03/08/2021
	No actionable defects found							
Batch:	20062599 - Inspection Batch			Route: NOR6M-2				Date: 10/02/2021
20042232	1 x CW patch. FW 2.5. CW 6	10/02/2021	Outside 79	CW02 ph <40 fast deterioration	Internal		Committed	20042041
Asset:	2,002.00	Asset - Locn.: U10801272/20 - FROM BROWNING STREET TO SINFIN LANE		Feature Type: Single 2-Lane Carriageway			Area: No code allocated	
Batch:	20120716 - Inspection Batch			Route: NOR6M-2				Date: 04/09/2024
20062051	1x CW patch	04/09/2024	Outside 64	CW02 ph <40 fast deterioration	Internal		Committed	20061937
	Please reinstate Road markings on patch							
Batch:	20120493 - Inspection Batch			Route: Ad Hoc Route				Date: 02/09/2024
20061989	1x temp large pothole repair- consider bringing wacker.	02/09/2024	Near Sinfin Lane	CW01 pothole >= 40	Internal		Committed	20061875
	(I have made an attempt with bagged tar but it needs alot more! Charlie is reporting water leak to STW							
Batch:	20114156 - Inspection Batch			Route: Ad Hoc Route				Date: 09/04/2024
20059845	Make safe potholes marked in patch due to resurfacing scheduled for 24/25 programme	09/04/2024	Outside 2	FW02 pothole >= 25	Internal		Committed	20059730
Batch:	20114155 - Inspection Batch			Route: Ad Hoc Route				Date: 09/04/2024
20059844	Make safe defect marked within patch by ramping tarmac, this is due to planned resurfacing works 24/25	09/04/2024	Outside 8	CW01 pothole >= 40	Internal		Committed	20059729
Batch:	20114154 - Inspection Batch			Route: Ad Hoc Route				Date: 09/04/2024
20059843	Make safe defect within marked patch by ramping with tarmac	09/04/2024	Outside 16	FW02 pothole >= 25	Internal		Committed	20059728
Batch:	20114122 - Inspection Batch			Route: NOR6M-2				Date: 09/04/2024
20059822	1x Fway patch	09/04/2024	Next to jnc Rawlinson Ave	CW01 pothole >= 40	Internal		Uncommitted	20059708
20059825	1x Fway patch	09/04/2024	Infront No.2	FW02 pothole >= 25	Internal		Uncommitted	20059707
20059824	Make safe 1x Cway pothole	09/04/2024	Opposite 35	CW01 pothole >= 40	Internal		Committed	20059710
20059823	1x Large Fway patch	09/04/2024	Outside 14 & 16	CW01 pothole >= 40	Internal		Uncommitted	20059709
Batch:	20113301 - Inspection Batch			Route: Ad Hoc Route				Date: 18/03/2024
20059413	1 x footway patch , install 2 x 10x5 kerbs and reset 1 x 10x5 kerb (Enquiry 10024032) Ill contact trees regarding the old stump	18/03/2024	Kitchener Avenue Adjacent 26	FW23 Fway Followup perm repai	Internal		Committed	20059296

Effective: 01/01/2021 to 26/11/2024

Display Action Officer: No

Site: KITCHENER AVENUE (10801272)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,002.00	Asset - Locn.:	U10801272/20 - FROM BROWNING STREET TO SINFIN LANE		Feature Type:	Single 2-Lane Carriageway	Area:	No code allocated
Batch:	20113299 - Inspection Batch		Route:		Ad Hoc Route		Date:	18/03/2024
20059411	Make safe 1 x footway pothole from snapped tree (Enquiry 10024032)	18/03/2024	Kitchener avenue Adjacent 26	TRE6 Tree dead within/adj Hwy	Internal		Committed	20059294
Batch:	20112993 - Inspection Batch		Route:		Ad Hoc Route		Date:	13/03/2024
20059317	CW patch x 1. 2 x 1.5. Cw 8 fw 2 Pothole - Large deep pot hole on Kitchner avenue just up from Sinfin Lane junction. External Ref: MA594899193 (Enquiry 20032472)	13/03/2024	Street: Kitchener Avenue Location: Hole is near to kerb side a few metres from the junction with Sinfin lane. Unavoidable if another vehicle on other side.	CW19 Cway Followup perm repai	Internal		Committed	20059200
Batch:	20112992 - Inspection Batch		Route:		Ad Hoc Route		Date:	13/03/2024
20059316	Temp x 1 CW Pothole - Large deep pot hole on Kitchner avenue just up from Sinfin Lane junction. External Ref: MA594899193 (Enquiry 20032472)	13/03/2024	Street: Kitchener Avenue Location: Hole is near to kerb side a few metres from the junction with Sinfin lane. Unavoidable if another vehicle on other side.	CW01 pothole >= 40	Internal		Committed	20059199
Batch:	20109132 - Inspection Batch		Route:		Ad Hoc Route		Date:	05/01/2024
20057795	CW patch 3.6 x 1 Cw 7 fw 1.8 on speed hump approach white line rqd Pothole - All along the humps on Kitchener avenue has plenty of potholes + the crossroad Kitchener avenue and browning street is extremely bad. A lady just lost her under car plastic tray. See photos and repair External Ref: MA574380940 (Enquiry 20031391)	05/01/2024	Street: Kitchener Avenue Location: All humps alongside + crossroad Kitchener av and browning str	CW19 Cway Followup perm repai	Internal		Committed	20057677
Batch:	20109131 - Inspection Batch		Route:		Ad Hoc Route		Date:	05/01/2024
20057794	Temp repair x 2 CW Pothole - All along the humps on Kitchener avenue has plenty of potholes + the crossroad Kitchener avenue and browning street is extremely bad. A lady just lost her under car plastic tray. See photos and repair External Ref: MA574380940 (Enquiry 20031391)	05/01/2024	Street: Kitchener Avenue junction Browning street Location: All humps alongside + crossroad Kitchener av and browning str	CW01 pothole >= 40	Internal		Committed	20057676

Effective: 01/01/2021 to 26/11/2024

Display Action Officer: No

Site: KITCHENER AVENUE (10801272)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,002.00	Asset - Locn.: U10801272/20 - FROM BROWNING STREET TO SINFIN LANE		Feature Type: Single 2-Lane Carriageway			Area: No code allocated	
Batch:	20109130 - Inspection Batch		Route: Ad Hoc Route				Date: 05/01/2024	
20057793	CW pTch x 2 1.5 x 17 and 1.5 x .7 white line reqd. Cw 7 fw 2 Pothole - All along the humps on Kitchener avenue has plenty of potholes + the crossroad Kitchener avenue and browning street is extremely bad. A lady just lost her under car plastic tray. See photos and repair External Ref: MA574380940 (Enquiry 20031391)	05/01/2024	Street: Kitchener Avenue os 51 Location: All humps alongside + crossroad Kitchener av and browning str	CW02 ph <40 fast deterioration	Internal		Committed	20057675
Batch:	20109128 - Inspection Batch		Route: Ad Hoc Route				Date: 05/01/2024	
20057791	CW patch x 1 .9 x .9. White line qd Pothole - All along the humps on Kitchener avenue has plenty of potholes + the crossroad Kitchener avenue and browning street is extremely bad. A lady just lost her under car plastic tray. See photos and repair External Ref: MA574380940 (Enquiry 20031391)	05/01/2024	Street: Kitchener Avenue os 33 Location: All humps alongside + crossroad Kitchener av and browning str	CW19 Cway Followup perm repai	Internal		Committed	20057673
Batch:	20105214 - Inspection Batch No actionable defects found		Route: NOR6M-2				Date: 10/10/2023	
Batch:	20099449 - Inspection Batch		Route: Ad Hoc Route				Date: 31/05/2023	
20054856	Whole footpath is deteriorating (Enquiry 20028973)	31/05/2023	Street: Kitchener Avenue Location: whole length,	CW06 fretting	Internal		Uncommitted	20054737
Batch:	20098560 - Inspection Batch		Route: NOR6M-2				Date: 15/05/2023	
20054558	1x CW patch on speed bump Please reinstate white road markings on patch.	15/05/2023	Outside 27	CW19 Cway Followup perm repai	Internal		Committed	20054440
20054559	Make safe 1x CW pothole	15/05/2023	Outside 27	CW01 pothole >= 40	Internal		Committed	20054439
Batch:	20096311 - Inspection Batch		Route: Ad Hoc Route				Date: 27/03/2023	
20053591	2 x carriageway patches (Enquiry 20027976)	27/03/2023	Street: Kitchener Avenue Location: outside 35	CW19 Cway Followup perm repai	Internal		Committed	20053471
Batch:	20090743 - Inspection Batch No actionable defects found		Route: NOR6M-2				Date: 01/12/2022	

Effective: 01/01/2021 to 26/11/2024

Display Action Officer: No

Site: KITCHENER AVENUE (10801272)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,002.00	Asset - Locn.: U10801272/20 - FROM BROWNING STREET TO SINFIN LANE		Feature Type: Single 2-Lane Carriageway			Area: No code allocated	
Batch:	20087697 - Inspection Batch		Route: Ad Hoc Route				Date: 21/09/2022	
20050715	Verge section is damaged but is being used as a cut through for pedestrians, make safe the trip hazard with tarmac. Also remove 2 x concrete sections at the PGR to ground level to lose trip. (Enquiry 10017971)	21/09/2022	Kitchener Avenue - junction Sinfin Lane	VER1 Verge damage	Internal		Committed	20050576
Batch:	20087696 - Inspection Batch		Route: Ad Hoc Route				Date: 21/09/2022	
20050714	Replace 1 x right hand dropper 1 x footway patch (Enquiry 10017971)	21/09/2022	Junction of Kitchener Avenue and Sinfin Lane and 20m up from Sinfin Lane	KB01Kerb missg/broken/crumble	Internal		Committed	20050575
Batch:	20083408 - Inspection Batch		Route: NOR6M-2				Date: 14/06/2022	
	No actionable defects found							
Batch:	20081428 - Inspection Batch		Route: Ad Hoc Route				Date: 09/05/2022	
20048961	Fw patch x 1 1.8 x 1.1. Cw 7 Fw 2 Where tree was , root base is soft and well rotted and pulls out easily	09/05/2022	Os 29	FW02 pothole >= 25	Internal		Committed	20048780
Batch:	20076370 - Inspection Batch		Route: NOR6M-2				Date: 31/01/2022	
	No actionable defects found							
Batch:	20076351 - Inspection Batch		Route: Ad Hoc Route				Date: 31/01/2022	
20047175	Fw patch and replace 3 10x5s	31/01/2022	O/S 7	FW03 ph <25 fast deterioration	Internal		Committed	20046994
Batch:	20076347 - Inspection Batch		Route: Ad Hoc Route				Date: 31/01/2022	
20047174	Fw patch	31/01/2022	O/S 2	FW03 ph <25 fast deterioration	Internal		Committed	20046993
Batch:	20069681 - Inspection Batch		Route: NOR6M-2				Date: 03/08/2021	
20044875	1 x FW patch. FW 2.8m CW 6.8m	03/08/2021	Opposite 39	FW03 ph <25 fast deterioration	Internal		Committed	20044687
Batch:	20062680 - Inspection Batch		Route: NOR6M-2				Date: 11/02/2021	
20042271	1 x CW patch. Patch on speed bump deteriorating and breaking away. FW 2 meters. CW 5.5 meters	11/02/2021	Outside 27	CW02 ph <40 fast deterioration	Internal		Committed	20042080