

Effective: 01/01/2018 to 17/12/2024
Site: COWSLEY ROAD (10800603)

Display Action Officer: No

Site: COWSLEY ROAD (10800603)

Locality: DERBY, DERBY CITY

Area: No code allocated

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,001.00	Asset - Locn.:	U05171_0603/010 - CARDIGAN STREET TO END	Feature Type:	Single 2-Lane Carriageway	Area:	No code allocated	
Batch:	20028239 - Inspection Batch		Route:	DERWENT 1 - SOUTH			Date:	25/07/2018
20022309		25/07/2018	Opp 149	Blacktop : fretting	Internal		Committed	20022106
20022308		25/07/2018	Os 209	Raised Profile	Internal		Committed	20022105
20022307	Repl 1no HB and 1no RH dropper	25/07/2018	Os 149	Half Battered Kerb Defect	Internal		Committed	20022104
20022313		25/07/2018	Os 123	Pothole	Internal		Committed	20022103
20022312		25/07/2018	Os 119	Blacktop : fretting	Internal		Committed	20022109
20022310		25/07/2018	Os 154	Blacktop : fretting	Internal		Committed	20022107
20022311		25/07/2018	Os 138	Blacktop : fretting	Internal		Committed	20022108
20022306	Provide and erect 4m barriers and signs around stone	25/07/2018	Os 154	Debris	Internal		Committed	20022102
Batch:	20024540 - Inspection Batch		Route:	Ad Hoc Route			Date:	23/04/2018
20018791	Replace damaged 6x5	23/04/2018	Street: Cowsley Rd o/s 121	Bull Nosed Kerb Defect	Internal		Committed	20018591
Batch:	20020682 - Inspection Batch		Route:	DERWENT 1 - SOUTH			Date:	16/01/2018
	No actionable defects found							
Asset:	1,002.00	Asset - Locn.:	U05745_0603/010 - CARDIGAN STREET TO END	Feature Type:	Single 2-Lane Carriageway	Area:	No code allocated	
Batch:	20030958 - Inspection Batch		Route:	Ad Hoc Route			Date:	10/10/2018
20024692	Take up and tip 0.2m cubed of stone and tip plus collect barriers and take to store	10/10/2018	Os 152	Debris	Internal		Committed	20024490
Batch:	20030957 - Inspection Batch		Route:	Ad Hoc Route			Date:	10/10/2018
20024691	Repl HB laid to slope levels cut where necessary lay level to fw	10/10/2018	Steps side 156	Half Battered Kerb Defect	Internal		Committed	20024489
Batch:	20028470 - Inspection Batch		Route:	DERWENT 1 - SOUTH			Date:	31/07/2018
	No actionable defects found							
Batch:	20020681 - Inspection Batch		Route:	DERWENT 1 - SOUTH			Date:	16/01/2018
20015215	Repl BN	16/01/2018	Os 147	Bull Nosed Kerb Defect	Internal		Committed	20015012
20015214	Raised	16/01/2018	Os 129	Raised Profile	Internal		Committed	20015011
20015213	Repl BN laid over drain cover	16/01/2018	Os 121	Bull Nosed Kerb Defect	Internal		Committed	20015010
20015225	Ph	16/01/2018	Os 109	Pothole	Internal		Committed	20015007
20015224	Make safe 2cw ph	16/01/2018	Os 114	Pothole	Internal		Committed	20015021
20015211	Ph	16/01/2018	Os 111	Pothole	Internal		Committed	20015008
20015221	Ph	16/01/2018	Os 154	Pothole	Internal		Committed	20015018
20015220		16/01/2018		Blacktop : extensive cracking	Internal		Uncommitted	20015017
20015219	Angle down kerb-take up tip and make safe concert at side 156	16/01/2018	On steps side	Half Battered Kerb Defect	Internal		Committed	20015016
20015212	Ph	16/01/2018	Os 119	Pothole	Internal		Committed	20015009
20015223	Phs	16/01/2018	Os 128	Pothole	Internal		Committed	20015020
20015217	Tree roots	16/01/2018	Jct Anglesey St	Raised Profile	Internal		Committed	20015014
20015216	Repl PCCE	16/01/2018	Os 189	PCC Edging Defect	Internal		Committed	20015013
20015222	Ph	16/01/2018	Jct Cardigan St	Pothole	Internal		Committed	20015019

Effective: 01/01/2018 to 17/12/2024
Site: COWSLEY ROAD (10800603)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,002.00		Asset - Locn.: U05745_0603/010 - CARDIGAN STREET TO END		Feature Type: Single 2-Lane Carriageway		Area: No code allocated		
Batch: 20020681 - Inspection Batch				Route: DERWENT 1 - SOUTH		Date: 16/01/2018		
20015218	Take out bricks and make safe	16/01/2018	Jct Hereford Rd	Raised Profile	Internal		Committed	20015015
Asset: 2,001.00		Asset - Locn.: U10800603/10 - FROM HAMPSHIRE ROAD TO END		Feature Type: Single 2-Lane Carriageway		Area: No code allocated		
Batch: 20118803 - Inspection Batch				Route: DER6M-1		Date: 22/07/2024		
20061491	1 x kerb, reset please!	18/07/2024	Outside 110	KB02 Kerb displaced/rocking	Internal		Committed	20061376
20061490	1 x Cw patch	18/07/2024	Outside 122	CW02 ph <40 fast deterioration	Internal		Committed	20061377
Batch: 20110394 - Inspection Batch				Route: Ad Hoc Route		Date: 22/01/2024		
20058222	1 x Cw patch	22/01/2024	Outside 130	CW02 ph <40 fast deterioration	Internal		Committed	20058104
Batch: 20110048 - Inspection Batch				Route: DER6M-1		Date: 18/01/2024		
No actionable defects found								
Batch: 20109140 - Inspection Batch				Route: Ad Hoc Route		Date: 05/01/2024		
20057803	1 x Cw patch	05/01/2024	Outside 116	CW01 pothole >= 40	Internal		Committed	20057685
Batch: 20101291 - Inspection Batch				Route: Ad Hoc Route		Date: 17/07/2023		
20055381	Reset bollard	17/07/2023	Street: Cowsley Road, at top Adj 209	M006 bollard damaged non-illum	Internal		Committed	20055262
Batch: 20100432 - Inspection Batch				Route: DER6M-1		Date: 22/06/2023		
20055110	1 x reset Kerb	21/06/2023	Outside 151	KB02 Kerb displaced/rocking	Internal		Committed	20054991
Batch: 20091157 - Inspection Batch				Route: DER6M-1		Date: 16/12/2022		
20051674	1 x Cw patch	16/12/2022	Outside 104	CW02 ph <40 fast deterioration	Internal		Committed	20051544
Batch: 20083795 - Ad Hoc Inspection Batch				Route: Ad Hoc Route		Date: 06/02/2022		
20049698	RTC - Clear debris, apply granules to oil spill, saw cut damaged barriers and put cones in place (Enquiry 10017006)	06/02/2022	outside 197 Cowsley Road, Chaddesden	M004 Spillage/contamination	Internal		Uncommitted	20049522
Batch: 20083179 - Inspection Batch				Route: DER6M-1		Date: 13/06/2022		
20049530	2x Cw patches	13/06/2022	Outside 128,127	CW02 ph <40 fast deterioration	Internal		Committed	20049354
Batch: 20075454 - Inspection Batch				Route: DER6M-1		Date: 06/01/2022		
20046868	2 x Cw patches	05/01/2022	Both outside 122	CW02 ph <40 fast deterioration	Internal		Committed	20046685
20046867	1 x Cw patch	05/01/2022	Outside 116	CW02 ph <40 fast deterioration	Internal		Committed	20046686
Batch: 20068268 - Inspection Batch				Route: DER6M-1		Date: 28/06/2021		
20044485	1 x Fw patch	25/06/2021	Outside house number 196	FW03 ph <25 fast deterioration	Internal		Committed	20044297
20044484	1 x Cw Patch	25/06/2021	Outside house number 132	CW02 ph <40 fast deterioration	Internal		Committed	20044298
Batch: 20059649 - Inspection Batch				Route: DER6M-1		Date: 13/11/2020		
20040824	1 x Fw patch	13/11/2020	Outside house number 214	FW03 ph <25 fast deterioration	Internal		Committed	20040634
Batch: 20053235 - Inspection Batch				Route: DER6M-1		Date: 05/06/2020		
20037852	1 x kerb reset. Make safe	04/06/2020	Outside house number 206	KB02 Kerb displaced/rocking	Internal		Committed	20037663
20037875	1 x Fw patch	04/06/2020	Outside house number 125	FW03 ph <25 fast deterioration	Internal		Committed	20037686
Batch: 20045933 - Inspection Batch				Route: Ad Hoc Route		Date: 28/11/2019		
20034313	Reset 1 x concrete bollard	28/11/2019	Next to house number 209 , turning point	M006 bollard damaged non-illum	Internal		Committed	20034124

Effective: 01/01/2018 to 17/12/2024

Display Action Officer: No

Site: COWSLEY ROAD (10800603)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,001.00	Asset - Locn.: U10800603/10 - FROM HAMPSHIRE ROAD TO END			Feature Type: Single 2-Lane Carriageway		Area: No code allocated	
Batch: 20045596 - Inspection Batch			Route: Ad Hoc Route				Date: 21/11/2019	
20034226	1x reset concrete post	21/11/2019	Next to house number 209. Turning point.	M010 Street furniture damaged	Internal		Committed	20034036
Batch: 20045537 - Inspection Batch			Route: DER6M-1				Date: 20/11/2019	
20034182	1x new kerb Hb	18/11/2019	Opposite house number 135	KB01Kerb missg/broken/crumble	Internal		Committed	20033992
Batch: 20037643 - Inspection Batch			Route: DER6M-1				Date: 09/05/2019	
20029127	3.0x0.6m fw patch	09/05/2019	Os 128	FW03 ph <25 fast deterioration	Internal		Committed	20028924
20029126	1.6x 0.5m 5x0.7m and 2.0 x0.7 m cw patches (3 no.)	09/05/2019	Os 114	CW02 ph <40 fast deterioration	Internal		Committed	20028923
20029125	0.6x0.3 and 3.8 x1.1m cw patches	09/05/2019	Os 124	CW02 ph <40 fast deterioration	Internal		Committed	20028922
20029130	0.8x0.3m cw patch	09/05/2019	Os 130	CW02 ph <40 fast deterioration	Internal		Committed	20028921
20029129	6.0x0.4m fw patch	09/05/2019	Os 152	FW03 ph <25 fast deterioration	Internal		Committed	20028926
20029128	5.1x2.0m fw patch	09/05/2019	Adj 133	FW03 ph <25 fast deterioration	Internal		Committed	20028925